Location: Muffy's Sys Fac ID: 13-00227

19 E MONTANA AVE Last Inspected On: 12/28/2015

BAKER, MT 59313 FALLON Operating Permit Renewal Date: 5/11/2019

Contact: Monica Stark, (406) 778-3144

(406)-778-3144 PO BOX 498

BAKER MT 59313-0498

Monica Stark, UST Class A Operator Roxann Janz, UST Class B Operator

Owners/Operators: Monica Stark, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	26	4/13/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
3519			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		9/26/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		11/12/2015	Gilbarco EMC Basic , Gilbarco		
6	17	10/1/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
3520			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		9/26/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		11/12/2015	Gilbarco EMC Basic , Gilbarco		

Location: J & A MINI STORE Sys Fac ID: 13-00685

116 W MONTANA AVE Last Inspected On: 10/28/2014

BAKER, MT 59313 FALLON Operating Permit Renewal Date: 3/25/2018

**Contact:** Arlene Heim, (406) 778-2411

(406)-778-2411 PO BOX 1300 BAKER MT 59313-1300

Rose Morast, UST Class A Operator Rose Morast, UST Class B Global Operator

Owners/Operators: Arlene Heim, Owner

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	26	5/24/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1447			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		9/25/2013	Automatic Tank Gauging 0.2	Deferred	
4,042			TLS-350/Gilbarco EMC , Veeder Root		
6	26	5/24/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1448			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		9/25/2013	Automatic Tank Gauging 0.2	Deferred	
9,954			TLS-350/Gilbarco EMC , Veeder Root		
7	26	5/24/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1449			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		9/25/2013	Automatic Tank Gauging 0.2	Deferred	
10,003			TLS-350/Gilbarco EMC , Veeder Root		

**Location:** FALLON COUNTY RD DEPT **Sys Fac ID:** 13-01687

122 E CENTER AVE Last Inspected On: 7/29/2015

BAKER, MT 59313 FALLON Operating Permit Renewal Date: 8/3/2018

**Contact:** Reiny Barth, (406) 778-2019

Owners/Operators: Fallon County Road Dept, Owner (406)-778-2019 PO BOX 1155

BAKER MT 59313-1155

Alba Higgins, UST Class A Operator Alba Higgins, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	22	6/9/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
896			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		9/13/2012	Manual Interstitial Monitor	Deferred	
6,000					
6	22	6/1/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
897			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		9/13/2012	Manual Interstitial Monitor	Deferred	
6,000					
7	22	6/1/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
898			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		9/13/2012	Manual Interstitial Monitor	Deferred	
3,000					

Location: PRAIRIE FUELS Sys Fac ID: 13-07740

176 E MILWAUKEE AVE Last Inspected On: 7/29/2015

BAKER, MT 59313 FALLON Operating Permit Renewal Date: 10/1/2018

Contact: Sharon Tronstad, (406) 778-3245

Owners/Operators: Prairie Fuels, Owner (406)-778-3245 PO BOX 1272

BAKER MT 59313-1272

Sharon Tronstad, UST Class A Operator Sharon Tronstad, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	19	9/1/1996	Bare Steel	Fiberglass	
3197	Yes	12/12/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
17,000			Other, Other		
6	19	9/1/1996	Bare Steel	Fiberglass	
3198	Yes	12/12/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
8,500			Other, Other		
7	19	9/1/1996	Bare Steel	Fiberglass	
3199	Yes	12/12/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,000			Other, Other		
8	19	9/1/1996	Bare Steel	Fiberglass	
3200	Yes	12/12/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,000			Other, Other		

Location: PRAIRIE FUELS Sys Fac ID: 13-07740

176 E MILWAUKEE AVE Last Inspected On: 7/29/2015

BAKER, MT 59313 FALLON Operating Permit Renewal Date: 10/1/2018

Contact: Sharon Tronstad, (406) 778-3245

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
9	19	9/1/1996	Bare Steel	Fiberglass	
3201	Yes	12/12/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
2,000			Other , Other		
10	19	9/1/1996	Bare Steel	Fiberglass	
3202	Yes	12/12/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
2.000			Other, Other		

Location: UNIVERSAL TIRE & ALIGNMENT

**Sys Fac ID**: 13-08221

908 E MONTANA AVE

Last Inspected On: 7/29/2015

BAKER, MT 59313 FALLON

**Operating Permit Renewal Date:** 8/3/2018

**Contact:** John Geving, (406) 978-2990

(406)-978-2990 PO BOX 500

BAKER MT 59313-0500

Owners/Operators: John Geving, Owner

John Geving, UST Class A Operator John Geving, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	16	8/1/1999	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4083			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		7/29/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Deferred	
8,000			Gilbarco EMC Basic , Gilbarco		
5	16	8/1/1999	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4084			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		7/29/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Deferred	
4,000			Gilbarco EMC Basic , Gilbarco		
6	16	8/1/1999	Bare Steel	Flexible Plastic	
4085	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		7/29/2015	Deferred	Continuous Interstitial Monitor	
5,500			Gilbarco EMC Basic , Gilbarco		

Location: FARMERS UNION OIL CO BULK PLANT BAKER **Sys Fac ID:** 13-09960

303 W MONTANA AVE

Last Inspected On: 12/28/2015 Operating Permit Renewal Date: 2/23/2019 **BAKER, MT 59313 FALLON** 

Kalvin Huether, (406) 778-2519 Contact:

Owners/Operators: Farmers Union Oil Co Baker, Owner PO BOX 1000 (406)-778-2519

BAKER MT 59313-1000

Tonya England, UST Class A Operator Calvin Huether, UST Class A Operator Travis Mashak, UST Class A Operator Barbara Stanhope, UST Class A Operator Tonya England, UST Class B Operator Calvin Huether, UST Class B Operator Travis Mashak, UST Class B Operator Barbara Stanhope, UST Class B Operator Tonya England, UST Class B Global Operator Travis Mashak, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	20	11/1/1995	Cathodically Protected Steel	Flexible Plastic	Positive Shutoff
977			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/28/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
5,000			TLS-450 , Veeder Root		
2	20	11/1/1995	Cathodically Protected Steel	Flexible Plastic	Positive Shutoff
978			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/28/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
10,000			TLS-450 , Veeder Root		

Location: FARMERS UNION OIL CO BULK PLANT BAKER

Sys Fac ID: 13-09960

303 W MONTANA AVE

BAKER, MT 59313 FALLON Operating Permit Renewal Date: 2/23/2019

Last Inspected On: 12/28/2015

**Contact:** Kalvin Huether, (406) 778-2519

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	20	11/1/1995	Cathodically Protected Steel	Flexible Plastic	Positive Shutoff
976			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/28/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
15,000			TLS-450 , Veeder Root		
<del></del>	20	11/1/1995	Cathodically Protected Steel	Flexible Plastic	Positive Shutoff
975			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		12/28/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
10,000			TLS-450 , Veeder Root		
10	20	11/1/1995	Cathodically Protected Steel	Flexible Plastic	Positive Shutoff
973			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		12/28/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
15,000			TLS-450 , Veeder Root		
11	20	11/1/1995	Cathodically Protected Steel	Flexible Plastic	Positive Shutoff
974			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/28/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
5,000			TLS-450, Veeder Root		

Location: FALLON COUNTY AIRPORT

**Sys Fac ID**: 13-10696

**FALLON COUNTY AIRPORT** 

Last Inspected On: 10/7/2015

BAKER, MT 59313 FALLON

**Operating Permit Renewal Date:** 2/9/2019

**Contact:** Roger Meggers, (406) 778-3508

Owners/Operators: Fallon County, Owner

(406)-778-3508 PO BOX 846

BAKER MT 59313-0846

Roger Meggers, UST Class A Operator

Roger Meggers, UST Class & Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	28	1/1/1988	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
894			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Kerosene		9/13/2012	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing, ELLD Line Tightness Testing	
10,000		10/7/2015	OPW 1500 , OPW	Automatic Tank Gauging 0.1	
2	28	1/1/1988	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
895			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		9/13/2012	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing, ELLD Line Tightness Testing	
10,000		10/7/2015	OPW 1500, OPW	Automatic Tank Gauging 0.1	

FALLON COUNTY MEDICAL COMPLEX **Sys Fac ID:** 60-15072 Location:

225 S 3RD ST W

Contact:

**BAKER, MT 59313 FALLON Operating Permit Renewal Date:** 7/13/2017

Brad Kings, (406) 778-5126

Owners/Operators: Fallon Medical Complex Inc, Owner/Operator PO BOX 820 (406)-778-3331

BAKER MT 59313-0820

Last Inspected On: 6/24/2014

Brad Kings, UST Class A Operator John Zook, UST Class B Operator John Zook, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	10	1/2/2006	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
5125			Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
2,500		6/24/2014	TLS-350/Gilbarco EMC , Veeder Root		